

DRILLING AND SERVICE BIG INSPECTION UNIT 001

Date of Inspection .March.16..1973..... Date of Last Inspection ..February.16..1973.
Well Name ..Chevron SOBC WM Whitefish YT J-70..... N67° 09' 32" Location W137° 26' 44"

卷之三

Donations in December - Details

Projected
Standard Data January 17, 1879

Month of last vaccine administered 12/3/81 at 00001

Conservation
Operators
Bert Chambers
Franklin
Consolidated
Management

Siempre se ha considerado que el desarrollo de la cultura es un factor de progreso y desarrollo social.

N.B.: See Page 2 - Remarks re items checked as "Unsatisfactory" or "No".

T. GENERAL
SEE COMMENTS ON PAGE 2

卷之三

N.Y.-B. & S. Saco Name 2 Bostonian 24 mo. oblong - 2 677.

18. Every driller has valid first aid certificate.

19. Air support for medical emergency

7.	Pick up slings	S	US	12.	Pop-out type nozzles on piping lines.	No
8.	Two exits from pumphouse	S	No	13.	Pop stack enclosed and heated.	
9.	Hose line from monkey board	S	US	14.	Manifold outside building are enclosed and heated.	
10.	Condition of hook latch	S	US	15.	Plastic boiler in piping system.	
11.	All derrick floor exits open outward from floor.	S	US	16.	High pressure lines, valves, fittings used on piping.	
12.	Seating valve adapters	Yes	No	17.	Accessibility of control valves handles.	
13.	Hoist eye bungy checked weekly and recorded.	Yes	No	18.	Convoy arrester for emergency circulation and preventive maintenance.	
VII. ENDS				19.	High pressure lines, valves, fittings on remote control units.	
				20.	Remote controls for all of systems than 75' from overhead.	
1.	Set time on bar type preventer	S	US			
2.	Set time on trans	S				
3.	Pressure test on bag type preventer	S	US			
4.	Pressure tests on pipe trans.	S	US			
5.	Pressure test on blind trans.	S	US			
6.	Valves open to manifold.	Yes	No			
7.	Pipe line tied down.	Yes	No			
8.	Accumulator hydraulic reservoir	S	US			
9.	Standby pressure source -	S	US			
10.	Nitrogen	Yes	No			
11.	Complaint witnessed	S	US			
12.	General crew knowledge of	S	US			
13.	Outdoors and kicks.	S	US			

2000 JOURNAL OF POLYMER SCIENCE: PART A: POLYMERS CHEMISTRY

The rig was generally inspected and found to be in a satisfactory condition.

The area damaged by fire, specifically under substructure, motor compound and draw works were inspected and the work performed reviewed with the operator. All repairs had been

The BOPI's and motions about certain economic issues