



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

RESOURCE MANAGEMENT DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Calgary, Alberta Date: 14th February 1969

TO: The Oil Conservation Engineer:

RE: Pan Am Beaver VM G-01

Location: 60°00'25" N., 124°15'45" W. Status: Drilling

This location was inspected by the undersigned on 14th February 1969

The location is in satisfactory/~~unsatisfactory~~ condition.

The following items require attention:

1. Move welder safe distance from rig.
2. Repair electrical fixture on floor heater.
3. B.O.P.s not working, unable to close blind rams, hydril slow to close.
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

Pipe rams and hydril would not close on Loffland 221.

Repairs to pipe rams to be carried out before drilling ahead. Circulation of hole may be done but no other activity until B.O.P.s are repaired.

The pipe rams and hydril would not operate because of a lack of pressure in the system. The fuse plug had been set in the "off" position and pressure had dropped in the hydraulic system. Repairs were carried out on the system and the rams and hydril were operating in a satisfactory manner when the writer left the drilling operations.

Inspected by [Signature]