



File No.....
Drilling Authority No.....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Amerada et al Crown Bell River YT - A No. 1 67-20-136-45

Location: 67° 19' 45" N., 136° 53' 29" W. Status: D & A September 1960

This location was inspected by the undersigned on 9th July 1971

T.D. 8004'


The location is ~~insatisfactory~~/unsatisfactory condition.

The following items require attention:

1. Perhaps 300 45 gal. bbls - some stacked, Bury or remove.
2. _____
3. Lumber to be piled and burned.
4. Cellar to be filled in. Piles to be cut off at G.L.
5. Paint identifier pipe and plate fluorescent orange.
6. Spread sawdust and bury all debris.

Other comments and recommendations: (Include Map, if necessary for clarity)

**Very bad condition.
No clean-up ever done here.
Garbage over 100 yd. radius from well.**



Inspected by *C. G. Thomas*