## WELLSITE INSPECTION REPORT

Your file Votre référence

Inspected by: .....

DISTRICT: 2	DATE OF INSPECTION: 3 Sept., 1972
WELLSITE NAME: Amerada et al	Crown Bell River "YT-A" No. 1
WELLSITE LOCATION: 67.32917°	N 136.89138° W
DRILLING AUTHORITY:	RIG RELEASE DATE: 1960
	STATUS: D & A
The location is in: ( ) Sati	sfactory (x) Unsatisfactory condition
The following items require yo	ur attention:
	wooden fallet, PLANKS
7,	LEMONE VIKUMS SARBAGE , CABLE , FIRE CUT-OF
2	DIVERT WATER COURSE ROLVOINE
	INTO \$ OUT OF Garbage put & restore.
	Control to the state of the state of
3	. Sorbage lowinal ffill required in sunker
	Camp garlogs pit
×	



	File	No.							•						
Drilling	Authority	No.	•	•	•	•				•		•	•		

## DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

## OIL AND MINERAL DIVISION

## **WELL-SITE INSPECTION REPORT**

FROM: Field Office or Area:	Date: 9th July 1971
TO: The Oil Conservation Engineer:	
RE:	
RE:Amerada et al Crown Bell River YF - A No. 1  Location: 67- 19: 45" No., 136- 53: 29" No. Status: BAA	
Location: 67° 19° 45" H., 136° 53° 29" W. Status: B & A	September 1960
This location was inspected by the undersigned on	
The location is in satisfactory/unsatisfactory condition.	T.D. 8004
The following items require attention:	
1,	
2. Perhaps 300 45 gal. bbls - some stacked, Bury or	remove.
3. Junk around well head to be removed.	
4. Lumber to be piled and burned.	
5. Celler to be filled in. Piles to be cut off at G.	
6. Paint identifier pipe and plate fluorescent orange	0.
Other comments and recommendations: (Include Midelies Recessary for clarity)	

Very bed condition. No clean-up ever done here. Garbage over 100 yd. radius from well.

Inspected by a Shual.

of IA & ND, Duplicate to Field Office or Inspecting Engineer.