OIL AND MINERAL DIVISION


RIG INSPECTION REPORT

TO BE COMPLETED AS REQUIRED

A. Contractor General Petroleums Rigs 15 Toolpusher Andy Sands

Well Name SOBC WM Shaeffer CkYT 0-22 Date and Time of Inspection 8:30 p.m., April 27/71

Operation in Progress Dummy trip before test Depth 10,370 Projected Total Depth 10,370



Location of BOP controls Hydril Remote on console, Pipe and Blind Rams in Accumulator House

What kind of test was witnessed? Mechanical X Pressure Describe test Well conducted Sump O.K. Unsatisfactory factory C. X Drilling 1. Is drilling authority posted? Authority 2. Was drilling authority issued before well spudded? Х 3. Does BOP equipment appear to be properly connected? X BLOWOUT 4. Are BOPs tested daily? X 5. Was equipment adequately pressure tested before drilling out casing shoe? PREVENTION Х to 1500' psi. 6. Did it appear all of crew knew how to operate equipment X EQUIPMENT 7. Is wellhead adequately heated for winter operation? X 8. Are bleed-off lines tied down? 9. Are distance requirements for following equipment satisfactory? X X (a) Boiler (150') FIRE (b) Open flame or electrical element heaters (75') (c) Flare pit to wellhead (150') HAZARDS (d) Oil or rubbish 75') Χ. 10. Are smoking regulation being observed?_ X TOUR REPORTS 11. Are tour reports satisfactory? Excellent X 12. Have required number of deviation surveys been run? X 13. Are there any apparent hazardous conditions on the rig⁹ MISCELLANEOUS 14. Does equipment conform to special H2S area requirements? X 15. Is well properly located with respect to buildings, roads, etc.? Х D. Remarks and Recommendations (Any action required of Calgary Office must be listed here.) Item No. Camp clean, First Aid Kit and Emergency Kit O.K.

l. Light Plant grounding, bar hooked to ground. 2. Spring loaded pump relief valves vented outside shelter. 3. 4. Motor shut down checked. 0.K. Remote control for hydril on driller's console. 5. Remote control for pipe and blind rams in Accumulator House. 6. Derrickman safety weight balance line. The second secon 7. Kelly cock O.K. Stabbing valve in doghouse. 8.

9. Smoking and Safety signs posted.

10. R.O.P. manifold outside substructure in plywood shelter - heater not hooked up.

11. N.B. Cameron guage on B.O.P. manifold should be lower range.

12. Light cover in pumphouse out and one cracked underfloor.

Field Office Calgary

Division Representative A.C. Anderson & G.E. Blue