



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: SOBC WM Schaffer Ck YT O-22

Location: 66.69833° N., 137.32778° W. Status: D & A, 1971

This location was inspected by the undersigned on 9th July 1971

The location is ~~in satisfactory condition.~~ unsatisfactory condition.

The following items require attention:

1. Reweld or set identifier in concrete - falling down.
2. Backfill sump.
3. Bury polyethylene sheeting.
4. Bury or pile and burn lumber
5. Paint identifier pipe and plate fluorescent orange.
6. Other comments and recommendations: (Include Map, if necessary for clarity)

Rig and equipment still on lease

File No. 464

Drilling Authority No. 464

CANADA

W-7940-1-464

Inspected by John Thomas

Original to Oil Conservation Engineer, Dept of IA & ND, Duplicate to Field Office or Inspecting Engineer. M. D. Thomas
FAND 52-90-14 (9-60)









10366



SCB 511
GRIFFITH
1970
10