



File No. ....  
Drilling Authority No. 240 .....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10 JUL 71

TO: The Oil Conservation Engineer:

RE: 10E SATAH River YT G-72-67-00-134-00

Location: 66.85778N 139.23250 Status: D&A<sup>Map</sup> 1967

This location was inspected by the undersigned on 10 July 71

The location is in satisfactory /unsatisfactory condition.

TD-7500

The following items require attention:

1. BURN EXISTING WOOD PILES
2. PAINT IDENTIFIER PIPE AND PLATE FLUORESCENT ORANGE.
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

WOOD PILED FOR BURNING

FILM NO 4  
35 MM (16) (17)

Inspected by \_\_\_\_\_



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

*N. 7940-1-240*

File No. .... 240 .....  
Drilling Authority No. ....

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: IOE Satah River YT G-72-67-00-134-00

Location: 66.85778° N., 134.23250° W. Status: D & A March 1967

This location was inspected by the undersigned on 10th July 1971

The location is in ~~unsatisfactory~~/unsatisfactory condition.

The following items require attention:

1. Burn existing wood piles
2. Paint identifier pipe and plate fluorescent orange.
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

\_\_\_\_\_

Inspected by *M. D. Thomas*

M. D. Thomas  
District 2



