



File No
Drilling Authority No.397.....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: INC Husky Amoco Blackfly YT M-55

Location: 65.91528° N., 140.4319 ° W. Status: D & A 1970

This location was inspected by the undersigned on 9th July 1971 T. D. 6790

The location is in ~~unsatisfactory~~ unsatisfactory condition.


The following items require attention:

- 1. All lumber to be piled and burned.
- 2. Hole in top of casing to be plugged.
- 3. Timber around cellar to be removed and cellar backfilled to a level above casing flange.
- 4. Pipe to be welded to top of casing.
- 5. Paint identifier pipe and plate fluorescent orange.

6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

- 7. Identifier pipe not welded - just hanging in hole in top of casing.
- 8. Stream erosion 50' from well.
- 9. Timbers, plastic sheeting, barrels, steel rope all to be buried



Inspected by M. D. Thomas
M. D. Thomas