



File No.
Drilling Authority No. 118

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT
OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 9 Jul 71

TO: The Oil Conservation Engineer:

RE: ~~SOCOMY~~ ^{SOCOMY} ~~MORIL ET AL~~ <sup>- WESTERN MINERALS
- W.M.I.E.</sup> PORCUPINE R. Y.T. - R-56

Location: 66.09261N 137.92560W Status: D&A 1963
66° 05' 33.4" — 137° 55' 32.2"

This location was inspected by the undersigned on _____

The location is in satisfactory/unsatisfactory condition.

TD 8500

The following items require attention:

1. ~~NO PIPE - NO IDENTIFIER~~
- 2.1 REMOVE PLANKING AROUND CELLAR AND ROCK FILL
- 3.2 PILE AND BURN ALL LUMBER
- 4.3 REMOVE OR BURY ALL BARRERS, SCRAP IRON & OTHER NON
- 5.4 DEGRADABLE ITEMS
- 6.5 PROVIDE MARKER MIN 2" PIPE WITH IDENTIFIER PLATE

Other comments and recommendations: (Include Map, if necessary for clarity)

2' x 3' BOLTED OR WELDED TO PIPE, MIN OF 4' ABOVE GL.

6. PAINT IDENTIFIER PIPE AND PLATE FLUORESCENT ORANGE

LEASE OVER GROWN BUT VERY JUNKY.

ABANDONED ^{STORAGE} TANK SITTING ON LARGE WOODEN PAD

SEVERAL BARRERS ON LEASE
PIPE
NO MARKER OR IDENTIFIER.

Film No 2
35 MM (14) (15) (16)

Inspected by _____



File No.....
Drilling Authority No.....118.....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil WM E. Porcupine R. YT K-56

Location: 66.09261° N., 137.92560° W. Status: D & A 1963

This location was inspected by the undersigned on 9th July 1971

T.D. 8500'

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Remove planking around cellar and backfill. Cut off all piles at ground level.
2. Pile and burn all lumber
3. Remove or bury all barrels, scrap iron, and other non-degradable items.
4. Provide marker, min. 2" pipe, with identifier plate 2' x 3' bolted or welded to pipe
5. minimum of 4' above G.L.
6. Paint identifier pipe and plate fluorescent orange.

Other comments and recommendations: (Include Map, if necessary for clarity)

- Remove tank.
- Lease overgrown but very junky.
- Abandoned storage tank sitting on large wooden pad.
- Several barrels on lease.
- No marker, pipe or identifier.

Inspected by _____

M. D. Thomas
District 2





