



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil Western Minerals Tuttle YT N-5 *100-30-26-75*

Location: 66.41422°N., 136.77297°W. Status: D & A July 1965

This location was inspected by the undersigned on 9th July 1971

The location is in ~~satisfactory~~ /unsatisfactory condition. T.D. 11,527'

The following items require attention:

- 1. Incorrectly identified.
- 2. Identifier to be welded or cemented on top of casing.
- 3. Remove storage tanks
- 4. Paint identifier angle and plate fluorescent orange.
- 5. Cut off all piles at G.L.
- 6. Burn or bury all lumber

Other comments and recommendations: (Include Map, if necessary for clarity)


- 7. Bury all scrap iron, pipe, etc.

Identified as SM-WM South Tuttle YT B-34

Lease never cleaned up.

2" x 3" angle iron used instead of 2" pipe. The angle iron was not welded to top of casing properly and has fallen off.

6 tanks on lease.



Inspected by *M. D. Thomas*

M. D. Thomas  
District 2