



File No.
Drilling Authority No. 139

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT
OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 9 JUL 72

TO: The Oil Conservation Engineer: W. Whitestone

RE: SOCONY MOBIL ~~WHITESTONE~~ YT N-26

Location: 66.09972N 138.3333W Status: D & A Aug 1964

This location was inspected by the undersigned on 9 July 71

The location is in satisfactory/unsatisfactory condition. TD 8085

The following items require attention:

1. PILE AND BURN ALL LUMBER
2. REMOVE PLANKING FROM AROUND CELLAR & BACKFILL.
3. REMOVE OR BURY ALL BITS, PIPE, STEEL ROPE ETC.
4. PAINT IDENTIFIER PIPE AND PLATE FLUORESCENT ORANGE.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

LEASE NEVER CLEANED UP
JUNK ALL OVER
~~BITS, PIPE, STEEL ROPE~~

Ch#2
35mm (11) (12) (13)

Inspected by _____



File No.
Drilling Authority No. 139

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil Western Minerals Whitestone YT N-26

Location: 66.09972° N., 138.33331° W. Status: D & A August 1964

This location was inspected by the undersigned on 9th July 1971

T.D. 8085'

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Pile and burn all lumber.
2. Remove planking from around cellar and backfill.
3. Remove or bury all bits, pipe, steel rope, etc.
4. Paint identifier pipe and plate fluorescent orange.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Lease never cleaned up. Junk all over.

Inspected by _____

M. D. Thomas
District 2





