

## DRILLING AND SERVICE RIG INSPECTION REPORT

Date of Inspection Apr. 72 Date of last inspection 13 Mar. 72

Well Name Kropic et al. well YT F-37 Location 66° 9' 40.55", 134° 8' 00.00"

Operating Company Kropic Lte. Contractor G. S. Farmer Rig No. 11

Operation in Progress Drilling Depth 10,600

Spud Date 13 Feb. 72 D.A. No. 547 Projected Total Depth 11,000

Depth of last casing string 13,378 ft or 11,000

Toolpush Jack Quirk Operators Bill Farmer Conservation R. J. Thomas  
Representative Bill Farmer Engineer R. J. Thomas

Signature Jack Quirk Signature Bill Farmer Signature R. J. Thomas

N.B.: See Page 2 - Remarks re items checked as 'Unsatisfactory' or 'Not'.

I. GENERAL

1. D.A. posted  Yes  No
2. Tour Reports complete, up to date and signed.  Yes  No
3. Location of wellsites with respect to natural & installed facilities  Yes  US
4. Sump adequately contained  Yes  No
5. Housekeeping  Yes  US
6. Radio communication in working order.  Yes  No
7. Camp & kitchen facilities clean and sanitary.  Yes  No
8. Adequate waste disposal  Yes  No
9. Deviation surveys every 500' minimum and recorded in tour book  Yes  No

II. SAFETY

1. Flare pit and burn pit greater than 150' from wellbore.  Yes  No
2. Boilers greater than 150' from the wellbore.  Yes  No
3. Rig lights operating and with protective covers.  Yes  No
4. Electrical fixtures within 75' of wellbore explosion proof.  Yes  No
5. Power plant grounded.  Yes  No
6. Adequate gas masks; Type: 6 Scott  Yes  No
7. Respirator with adequate supply of air.  Yes  No
8. Minimum of one powder fire extinguishers in dormouse.  Yes  No
9. Minimum of two ~~5 lb.~~ CO<sub>2</sub> fire extinguishers in each boiler house.  Yes  No
10. Fire extinguishers in camp.  Yes  No
11. First aid kits; No.:  Yes  No
12. Safety goggles  Yes  US
13. Scratches and blankets  Yes  No
14. All moving parts safely guarded  Yes  No
15. Necessary guard rails in place  Yes  No
16. Safety meeting held and recorded in tour book.  Yes  No
17. Fuel storage greater than 75' from wellbore.  Yes  No
18. Every driller has valid first aid certificate.  Yes  No
19. Air support for medical emergency.  Yes  No

20. Fireproof material in rig shelter  Yes  No
21. Wiring high enough above ground for clearance.  Yes  No
22. Hard hats worn on rig or in potentially dangerous areas.  Yes  No
23. All breathing apparatus tested monthly & recorded in tour book.  Yes  No

III. MUD SYSTEM

1. Mud tank capacity  Yes  US
2. Safety valve on pump discharge line Type: Domes 8" float  Yes  US
3. Mud weight relative to depth.  Yes  US
4. Gas analyzer.  Yes  US
5. Degasser, if mud tanks in rig shelter  Yes  No
6. Mud level warning system. Ty. alarm  Yes  US
7. Condition of Kelly hose.  Yes  US
8. Mud mixing platform clean.  Yes  No
9. Studs and nuts on fluid cylinder head and valve covers.  Yes  US
10. Pressure rating of mud discharge line  Yes  US
11. Mud gun anchors.  Yes  US

IV. ENGINES AND FUEL

1. Condition of motors  Yes  US
2. Engine air inlets greater than 40' from wellbore.  Yes  No
3. Engine exhausts greater than 40' from wellbore.  Yes  No
4. Where engine exhausts exceed 40', such exhausts less than 75' from wellbore are insulated.  Yes  No
5. Motor safety shut down on floor.  Yes  US
6. Condition of fuel lines.  Yes  US
7. Shut-offs checked weekly and recorded on tour sheets.  Yes  No
8. Water connections on engine exhausts working.  Yes  No

V. FLOOR AND DERRICK

1. Stubbing valves handy.  Yes  No
2. Kelly cock operation.  Yes  US
3. Emergency alarm.  Yes  US
4. Tong lines and tong dies.  Yes  US
5. Rotating line examined weekly and recorded in tour book.  Yes  US
6. Exits from all four sides of rig floor.  Yes  O

# Pacific class well ST F-37

Page 2 of 4

I.	Deck up aligned.	US	12. BOP's tested before drilling out.	US
II.	No events from purifier house.	No	13. BOP's enclosed and heated.	US
III.	Steering line from monkey board.	US	14. Manifold outside substructure enclosed and heated.	US
IV.	Condition of hook latch.	US	15. Flange bolts in place & tightened.	US
V.	All derrick floor exits open outward from floor.	No	16. High pressure lines, valves, fittings used on BOP's.	US
VI.	Stabilizing valve adapters.	No	17. Accessibility of control valve handles.	US
VII.	Hoist & buggy checked weekly and recorded.	No	18. Control arms for manually closing ram type preventer outside substructure.	US
VIII.	BOP's		19. High pressure lines, valves, fittings on remote control unit.	US
IX.	1. S.I. time on bag type preventer	US	20. Remote controls for BOP's greater than 75' from wellbore.	US
X.	2. S.I. time on rams	US		
XI.	3. Pressure test on bag type preventer.	US		
XII.	4. Pressure test on pipe rams.	US		
XIII.	5. Pressure test on blind rams.	US		
XIV.	6. Valves open to manifold.	No		
XV.	7. Flare line tied down.	No		
XVI.	8. Accumulator hydraulic reservoir	US		
XVII.	9. Standby pressure source - ie: Nitrogen	US		
XVIII.	10. BOP drill witnessed	No		
XIX.	11. General crew knowledge of blowouts and kicks.	US		

## VII. ELECTRICAL

1. All light fixtures and wiring in good condition
2. Light plant adequate for job.
3. Standby light plant.

\* Satisfactory

\*\* Unsatisfactory

REMARKS RE: ITEM'S CHECKED AS 'UNSATISFACTORY' OR 'NO':

I would like to see the line from the stack to the manifold replaced with a straight line. To accomplish this manifold would have to be beyond pipe racks or perhaps the spool could be below the upper BOP. Bull plough tee could be used. This rig is well above the average in the area in terms of housekeeping.

Note Sheets 3 & 9 were completed as nothing has been changed from last inspection.

Note. The bull plug referred to above, if used should be leaded.