



File No.
Drilling Authority No. ... 348

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

RESOURCE MANAGEMENT DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Calgary, Alberta Date: 14th February 1969

TO: The Oil Conservation Engineer:

RE: Pan Am Merrill YT J-67

Location: 60°16'30" N 124°27'00" W Status: Drilling at 3261'

This location was inspected by the undersigned on 14th February 1969

The location is in satisfactory/~~unsatisfactory~~ condition.

The following items require attention:

1. Remove grinder from doghouse.
2. Install vapour-proof light in doghouse.
3. Anchor flare line.
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Brinkerhoff 42H

Hydril and Pipe Rams mechanical check satisfactory.