

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: SHELL PEELE R YT K-9 66-20-234-00

Location: 66.30992°N., 134.01728°W. Status: DEA March 1967

This location was inspected by the undersigned on 10th July 1971

The location is in satisfactory/unsatisfactory condition. TD 5100'

The following items require attention:

- 1. Pile and burn all lumber
- 2. Bury or remove all drums, scrap iron and wire rope.
- 3. Paint identifier pipe and plate fluorescent orange.
- 4. _____
- 5. _____
- 6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Identified as Shell Peel K-9

1" pipe stead of minimum 2"

Lease never cleaned up

Sump never backfilled

15 drums on lease

4 coils wire rope



Inspected by *M. D. Thomas*
 M. D. Thomas
 District 2