



CANADA  
DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

Location: 66.81091° N., 135.30659° W. Status: D & A December 1966

This location was inspected by the undersigned on 10th July 1971

T.D. 6500'

The location is in ~~satisfactory~~/unsatisfactory condition.


The following items require attention:

1. Bury steel drums, wire rope, etc.
2. \_\_\_\_\_
3. \_\_\_\_\_

6. \_\_\_\_\_  
Other comments and recommendations: (Include Map, if necessary for clarity)

**Lease grown over.**  
**Sump not filled in - some junk in sight: 3 bbls. and wire rope.**

**Bead on Pipe - Shell L-19**



Inspected by W. J. Donald