



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: SOBC Blackstone YT D-77

Location: 65.76966°N., 137.24855°W. Status: D & A January 1963

This location was inspected by the undersigned on 9th July 1971

T.D. 13,217'


The location is in ~~unsatisfactory~~/unsatisfactory condition.

The following items require attention:

1. Incorrectly identified
  2. Identifier pipe to be welded to top of casing or placed in cement block above casing.
  3. Paint identifier pipe and plate fluorescent orange.
  4. Cut off piles flush with G.L. Backfill cellar.
  5. Pile and burn all lumber
  6. Bury or remove all iron, sacks (stacked on wooden platform) steel drums and other junk.
  7. Remove storage tank.
- Very bad lease, never cleaned up.

Identifie as Cal-Std YT D-77

Looks like there was a fire here.



Inspected by M. D. Thomas  
M. D. Thomas  
District 2