



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10 Jul 71

TO: The Oil Conservation Engineer:

RE: TOLTEC PEELE R 47 N-77

Location: 65.94611 N 134.48666 W Status: D&A 1970

This location was inspected by the undersigned on _____

The location is in satisfactory/unsatisfactory condition. TD 3683'

The following items require attention:

1. PROVIDE IDENTIFIER PIPE, 2" MIN DIAMETER, WITH IDENTIFIER
2. PLATE 2'x4' WELDED OR BOLTED TO PIPE MIN OF 4' ABOVE
3. GL. PIPE TO BE WELDED TO TOP OF CASING OR SET IN CONCRETE ABOVE
4. CASING. PAINT IDENTIFIER PIPE AND PLATE FLUORESCENT ORANGE.
5. REMOVE DRUMS ALONG SHORELINE
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

HEAVY SMOKE - HAD TO FOLLOW RIVER. DIFFICULT TO SEE.
IDENTIFIED AS - TOLTEC 47 N-77

GOOD CLEANUP BUT OVER 100 STEEL DRUMS
LEFT PLUS LUMBER AND CAMP SHACKS. (SEE ATTACHED LETTER)

1" PIPE ONLY 2 1/2 FT LONG NOT
WELDED ^{TO CASING}. CANNOT TELL WHERE HOLE IS.
50 YARDS FROM
~~RIGHT~~ ON PEELE RIVER.

IS LOCATION RIGHT? ON OPPOSITE SIDE OF RIVER

A FEW DRUMS ON SHORE LINE WHICH WILL BE
SWEEP DOWN RIVER WHEN RIVER RISES

~~6 CABINS & CONTENTS LEFT FOR INDIANS~~

35MM (19) (20) (21)

GLM NO 5: 17, 18, 19

Inspected by _____



File No.
Drilling Authority No. ... 321.

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT
OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: Toltec Peele R. YT N-77

Location: 65.94611°N., 134.48666°W. Status: D & A 1970

This location was inspected by the undersigned on 10th July 1971

The location is ~~in satisfactory~~ /unsatisfactory condition. T.D. 3683'

The following items require attention:

1. Provide identifier pipe, 2" minimum diameter with identifier plate 2' x 4' welded
2. or bolted to pipe min. of 4' above G.L. Pipe to be welded to top of casing or set
3. in concrete above casing. Paint identifier pipe and plate fluorescent orange.
4. Remove drums ^{and raft} along shoreline.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Heavy smoke - had to follow river. Difficult to see.
Identified as - Toltec YT N-77

Good clean-up but over 100 steel drums left plus lumber and camp shacks (See attached letter).

Inspected by *M. D. Thomas*
M. D. Thomas
District 2



PINNACLE PETROLEUMS LTD.

3RD FLOOR, 703 - 5TH ST. S.W. - CALGARY 2, ALBERTA
TELEPHONE 403 - 264-6063

June 18, 1971

Department of Indian Affairs
& Northern Development
112 - 11 Avenue S. E.
CALGARY 21, Alberta

Attention: Mr. M. D. Thomas
District Conservation Engineer

Gentlemen:

Re: Cleanup, Toltec Peel River YTN 77

This letter is to confirm our telephone conversation of yesterday's date in which you gave the approval of your Department to the plans of Pinnacle Petroleum as set out below.

Pinnacle Petroleum Ltd. is removing a drilling rig and various auxiliary equipment from the captioned lease and restoring the lease to the satisfaction of the Department of Indian Affairs & Northern Development.

At the well site is a camp consisting of six shacks of wood, styrofoam and fibreglass construction. Because the cost of removing this camp is in excess of its actual value and because the camp is of use to the local Indian band, it is the intent of Pinnacle to leave the camp on the site. The legal responsibility for and the title to this camp in the future will be held by Mr. Fred Blake of Ft. McPherson, a representative of the local band.

Very truly yours,

PINNACLE PETROLEUMS LTD.

J. R. Schmid
Vice-President

JRS/ld







