

File	No
Drilling Authority	No

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM:	Field Office or Area: Nuvik. District #2 Date: September 21, 1972
XXXXXX	XYOURIST ACTURET ACTUR
RE:	(Western Minerals) Peel Plateau Eagle Plains YT #1 (66-50-138-00)
Locatio	on: 66-48-54 — 138-08-30 Status; Suspended 8-7-58
This lo	cation was inspected by the undersigned onAugust 24, 1972
The loc	cation is investisfactory/unsatisfactory condition.
The fol	llowing items require attention:
1.	Piles of junk and scrap metal to be buried.
2.	Wood debris to be burned.
3.	Platform around well head to be tidied up or dismantled and buried.
4.	Sawdust pile to be levelled.
_	Sign to be affixed to well head.
6.	
Other c	comments and recommendations: (Include Map, if necessary for clarity)
No	ote: There appears to be another site adjacent to this one which has scrap metal and
	junk over entire area, including an abandoned building. The Operator is responsible
	for this site or sites which he has used only.

Inspected by _____ Colors

D. A. Bohun

Department of Indian Affairs and Northern Development



Ministère des Affaires indiennes et du Nord canadien

WELLSITE INSPECTION REPORT

DISTRICT:

DATE OF INSPECTION:

WELLSITE NAME: Pecel Eagle Planns YT#/

WELLSITE LOCATION:

DRILLING AUTHORITY: None

STATUS:

The location is in () Satisfactory

(Unsatisfactory condition.

COMMENTS: #14 A welleas & platform 4111

\$16 v from ani

Ks identifica Valves not locked

INSPECTED BY:

M. D. Thomas Regional Oil & Gas Engineer











