



File No. ....  
Drilling Authority No. .... NA .....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Western Minerals Chance YT No. 1 66-0-131-31

Location: 66.12944°N., 137.52425°W. Status: Suspended gas or oil May 1960

This location was inspected by the undersigned on 9th July 1971

T.D. 8648'


The location is in ~~unsatisfactory~~ satisfactory condition.

The following items require attention:

1. Provide identification
2. Chain and lock the three bottom valves
3. Remove platform and cut off all piles at G.L.
4. Burn or bury all lumber on lease
5. Bury all scrap iron, etc.
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

Sump not filled in.



Inspected by M. D. Thomas  
M. D. Thomas  
District 2