



CANADA

File No. ....  
Drilling Authority No. ....

File No. ....  
Drilling Authority No. ....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

### WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 20th July 1971

TO: The Oil Conservation Engineer:

RE: IOE Blow River YT E-47

Location: 68.77222°N., 137.45361°W. Status: D & A 1970

This location was inspected by the undersigned on 8th July 1971

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Paint identifier fluorescent orange.

2. Either backfill and cover piles or cut off at G.L.

3.

4.

5.

6. Other comments and recommendations: (Include Map, if necessary for clarity)

Clean-up crew at site. Burning and backfilling. Expect another week of clean-up. Bob McElroy, Foreman, for IOE.

Inspected by Le Shaeel

Original to Oil Conservation Engineer, Dept of IA & ND, Duplicate to Field Office or Inspecting Engineer.  
LAND 52-90-14 (Q.E.O.)

M. D. Thomas  
District 2







