

DRILLING AND SERVICE RIG INSPECTION REPORT

Date of Inspection Jan. 14, 1973. (12 months of last inspection) ...Nil.....
 Drill Site Pacific IMP. et al. Roland Bay YT L-41..... Location 69° 20' 30.0' N.
 138° 56' 55.092" W. Mic No. 25.....
 Operator Company Pacific Petroleum... Contractor Naftex.....
 Position in Progress Drilling (Fishing). Depth 628'.... Milling on iron.....
 Date Dec. 22, 1972. (4:00 p.m.) D.A. No. 627..... Total Depth 10,000'
 Length of last casing string 20' x 14# at 456'.. Ran Jan. 10, 1973
 Operators Conservation
 Technican G. Barnhurst..... Representative Bill Farmer..... Engineer G. E. Blug.....
 T. Rinder Signature Signature

At time of inspection - running in with magnet.

Note: See page 2 - remarks re items checked as 'Unsatisfactory' or 'No'.

1.	1. All tested	Yes	No	20. Fireproof material in rig shelter	Yes
2.	2. Our reports complete, up to date	Yes	No	21. Wiring high enough above ground for clearance.	Yes
3.	3. Surface of wellsite with respect to safety & installed facilities	Yes	No	22. Hard hats worn on rig or in potentially dangerous areas.	Yes
4.	4. Tools adequately contained	Yes	No	23. All breathing apparatus tested monthly & recorded in tour book.	Yes
5.	5. Tools marking	Yes	No		
6.	6. Radio communication in working order.	Yes	No		
7.	7. Kitchen facilities clean and sanitary.	Yes	No	I. MUD SYSTEM	
8.	8. Complete waste disposal	Yes	No	1. Mud tank capacity	Yes
9.	9. Location surveys every 300'	Yes	No	2. Safety valve on pump discharge line	Yes
10.	10. and recorded in tour book	Yes	No	Type:	Yes
11.	11. at 628'	Yes	No	3. Mud weight relative to depth.	Yes
12.	12.	Yes	No	4. Mud polymer.	Yes
13.	13. Mud pit and turn pit greater than 10' from wellbore.	Yes	No	5. Number, if mud tanks in rig shelter	Yes
14.	14. greater than 150' from wellbore.	Yes	No	6. Mud level warning system. Type:Mat	Yes
15.	15. operating and with protective cover.	Yes	No	7. Condition of Kelly hole. Decker	Yes
16.	16. Structural fixtures within 75' of wellbore explosion proof.	Yes	No	8. Mud mixing platform clean.	Yes
17.	17. (SEE NOTE)	Yes	No	9. Studs and nuts on fluid cylinder heads and valve covers.	Yes
18.	18. Power plant grounded.	Yes	No	10. Pressure rating of mud discharge	Yes
19.	19. Adequate gas masks; Type Scott Air	Yes	No	11. Mud gun anchors.	Yes
20.	20. Ventilator with adequate pack of air.	Yes	No		
21.	21. Location of two 3" power fire main checkers in nozzles.	Yes	No	IV. IGNITION AND FUEL	
22.	22. Location of two 9 in. CO ₂ fire main checkers in each trailer	Yes	No	1. Condition of motors	Yes
23.	23. 8 in.	Yes	No	2. Engine air inlets greater than 40' from wellbore.	Yes
24.	24. main checkers in camp building	Yes	No	3. Engine exhausts greater than 40' from wellbore.	Yes
25.	25. First aid kits; K.A.B.C. Industrial supplies & 2MSA Safety	Yes	No	4. Where engine exhausts exceed 40' & such exhausts less than 75' from wellbore are insulated	Yes
26.	26. Protection and blankets	Yes	No	5. Motor safety shut down on floor.	Yes
27.	27. All covers; parts safely secured	Yes	No	6. Condition of fuel lines.	Yes
28.	28. any sharp metal in place	Yes	No	7. Shut-offs checked weekly and recorded on tour sheets.	Yes
29.	29. Safety chain; bell & recorded in tour book.	Yes	No	8. Water connections on engine exhausts working.	Yes
30.	30. greater than 75' from wellbore.	Yes	No		
31.	31. If Miller has valid first aid certificate Checked w/tool pusher	Yes	No	V. FIRE & MUD SAFETY	
32.	32. M.R. support for medical emergency	Yes	No	1. Stabilizing valves handy.	Yes
				2. Kelly cock operation.	Yes
				3. Emergency alarm.	Yes
				4. Tong lines and tongs.	Yes
				5. Hoisting line examined weekly and recorded in tour book	Yes
				6. Exits from all four sides of rig floor.	Yes

* Satisfactory
** Unsatfactory

1.	100' test before drilling out.
2.	Well name enclosed and noted.
3.	Manifold outside structure colored and painted. Not hooked up.
4.	Drill bit in place - thumbtack.
5.	High pressure lines, valves, fitting cleaned air tight.
6.	Operability of control valve checked.
7.	Control arm for manually closing valve type prevent's outlet contamination.
8.	High pressure lines, valves, fitting or remote control unit.
9.	Remote controls for wells greater than 75' from wellbore.
<u>V.I. - Well Site</u>	
1.	All right fixtures and wiring in good condition.
2.	Right plant required for job.
3.	Handy right people.

SUMMARY OF THE INVESTIGATION AND CONCLUSIONS

1. Remove grinder from doghouse.
 2. Drilling authority to be posted in the doghouse.
 3. Instructed toolpush to enter safety meetings in tour book.
 4. Tie flare line down and extend to 150'. Mud pallets Flare line O. K.
 5. Mr. Farmer was asked to improve radio communications with Inuvik. This will be looked into by Pacific.
 6. Toolpush was informed that housekeeping should be improved before the next inspection.