

	File	No.				۰	٠			à	٠,	0.			a	۰	b	
Drilling	Authority	No.	,	L	9.	8	9	۰	0				a	æ		a	*	

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

CANADA	willing rolling try troes of for to excess as a
DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN	DEVELOPMENT
OIL AND MINERAL DIVISION	RT N-3940-1-198
WELL-SITE INSPECTION REPOR	RT
FROM: Field Office or Area: Inuvik	Date: 9th July 1971
TO: The Oil Conservation Engineer:	
RE: SOBC WM E. Porcupine YT I-13	
Location: 66.04330° N., 137.78278 ° W. Status: D & A	1971
This location was inspected by the undersigned on 9th July 1971	T.D. 8004 t
The location is in satisfactory/unsatisfactory condition.	
The following items require attention:	
1. Sump to be filled in	
2. Bury or remove all non-degradables	
3. Lease to be levelled.	
4.	
5.	
6.	
Other comments and recommendations: (Include Map, if necessary for clarity)	

Equipment still on lease Lease relatively clean







