

Well Site # 2

Chevron SOBC WM N Parkin YTD-61

Location 66°20'12"
137°13'01"

Drilling completed May 6, 1972




Photo # 6 N Parkin YTD_61 September 10, 1975

This wellsite has not revegetated as well as the W Parkin YTC-33 site.

The introduced grasses are found in densely concentrated clumps around the well marker. The remainder of the site is patchy with mostly natural regeneration.

The concentrations of lush timothy near the well head (see Photo #7) leads one to believe that an excessive amount of nitrogen fertilizer was applied.

Possibly this reseeding job was done on a Friday afternoon?

The arrow in Photo #6 indicates the reseeded grasses on the wellsite.



Photo # 7 N Parkin YTD-61 September 10, 1975

This thick mat of timothy has been repeatedly browsed by moose.



