



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: September 21, 1972

~~TO: The Oil Conservation Engineer:~~

RE: Socony Mobil Western Minerals E. Porcupine R. YT K-56 (66-10-137-45)

Location: 66-05-33 — 137-55-32 Status: D & A 23-7-63

This location was inspected by the undersigned on August 24, 1972

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Piles to be cut down at ground level.
2. Sign to be affixed to well.
3. 15 individual piles of junk to be buried.
4. Remains of tank to be disposed of.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Please note that it is reported that the lumber on the airstrip belongs to Globe.

Inspected by *D. A. Bohun*

D. A. Bohun















