

	Fil-	No.								
Drilling	Authority	No.	٠.	زند	H					

## DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

## OIL AND MINERAL DIVISION

## WELL-SITE INSPECTION REPORT

FROM: Field Office or Area:	_ Date: 9th July 1971							
TO: The Oil Conservation Engineer:								
RE:SOCONY MOBIL WESTERN MINERALS MOLAR YT P-34								
Location: 67.06639° N., 138.60000° W. Status: D&A	August 1964							
This location was inspected by the undersigned on9th July 1971								
The location is in satisfactory/unsatisfactory condition.	<b></b>							
The following items require attention:	TD 8704'							
1.								
2.								
3.								
4.								
5.								
ú.								
Other comments and recommendations: (Include Map, if necessary for clarity)								

Could not locate. If known, a description of terrain and condition of site should be sent to this office to aid in locating site on next inspection trip.

M.D. TIOMAS, District 2

M.D. THURING, Manuervation Engineer, Dept of IA & ND, Duplicate to Field Office or Inspecting Engineer, Mattic 23:20年14 (2:53)