



File No.
 Drilling Authority No. ... 148

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT
 OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: September 21, 1972

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~
~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~
 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

RE: Socony Mobil Western Minerals S. Tuttle YT N-5 (66-30-136-45)

Location: 66-24-51 — 136-46-23 Status: D & A 8-7-65

This location was inspected by the undersigned on August 24, 1972

The location is ~~in satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Dismantled tanks, drums, and other heavy metal and scrap metal piles to be buried.
2. Drill bit cuttings to be levelled.
3. Large pile of garbage and debris to be buried.
- 4.
- 5.
- 6.

Other comments and recommendations: (Include Map, if necessary for clarity)

Inspected by *D. A. Bohun*
 D. A. Bohun