



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil WM N Cath YT B-62

Location: 66.18708° N., 138.69805° W. Status: D & A June 1965

This location was inspected by the undersigned on \_\_\_\_\_

T.D. 7016'

The location is in ~~satisfactory~~/unsatisfactory condition.


The following items require attention:

1. Shack and storage tank to be removed
2. 4 storage tanks 1/2 mile away to be removed
3. Flare pit to be filled in - junk in pit
4. 6 45 bbl. drums to be buried or removed
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

Turned over to Dept. of M & T S.

Drilling mud around well head.



Inspected by M. D. Thomas  
M. D. Thomas  
District 2