

File	No		
Drilling Authority	No	156	• • • • • • • • •

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: August 24, 1972
MO:XLPKINKCPHSSHATINGK ENflurre
RE: Socony Mobil Western Minerals Birch YT R-34 (66-10-136-45)
Location: 66-03-03 136-51-18 Status: "Protectively Plugged Gas Well" 8-6-65
This location was inspected by the undersigned onAugust 24, 1972
The location is in wattsfactory/unsatisfactory condition.
The following items require attention:
1. Piles of scrap metal and junk to be buried.
2. Piles of wood and combustibles to be burned.
3. Piles to be cut off as close to ground level as possible.
4. One small shallow depression to be filled in.
5.
6.
Other comments and recommendations: (Include Map, if necessary for clarity)

Except for the individual piles of junk, the lease is in very good condition, however, the numerous piles require burial.

Inspected by . O al Dohum