



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

N-7940-1-14

File No. .... 144 .....  
Drilling Authority No. ....

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil Western Minerals Ellen YT C-24

Location: 66.55246°N., 137.83559°W. Status: D & A April 1965

This location was inspected by the undersigned on 9th July 1971

The location is in ~~satisfactory~~ unsatisfactory condition. T.D. 7134'

The following items require attention:

1. Identifier fallen over - replace.
2. Bury black plastic sheeting, steel drums, wire rope, scrap iron and other junk
3. Pile and burn all lumber.
4. Paint identifier pipe and plate fluorescent orange.
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

*(photos attached)  
08/02/77 AS*

Inspected by *M.D. Thomas*  
M.D. Thomas  
District 2





























