



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

File No. ....  
Drilling Authority No. .... 139 .....

*N-7940-1-139*

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil Western Minerals Whitestone YT N-26

Location: 66.09972° N., 138.33331° W. Status: D & A August 1964

This location was inspected by the undersigned on 9th July 1971

T.D. 8085'

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. File and burn all lumber.
2. Remove planking from around cellar and backfill.
3. Remove or bury all bits, pipe, steel rope, etc.
4. Paint identifier pipe and plate fluorescent orange.
5. \_\_\_\_\_
6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

**Lease never cleaned up. Junk all over.**

Inspected by: *M. D. Thomas*  
M. D. Thomas  
District 2