



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: September 21, 1972

~~TO: THE OIL CONSERVATION ENGINEER~~

RE: Socony Mobil Western Minerals Whitestone YT N-26 (66-10-138-15)

Location: 66-09-59 — 138-20-00 Status: D & A 6-8-64

This location was inspected by the undersigned on August 24, 1972

The location is in ~~satisfactory~~ unsatisfactory condition.

The following items require attention:

1. Drill cuttings pile should be levelled.
2. 3 individual small piles of scrap metal to be buried.
3. One large pile of debris to be buried.
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Note that pilings have been cut to within reasonable distance of ground level and rathole is still in place, however, this is considered satisfactory under the circumstances.

Inspected by *D. A. Bohun*

D. A. Bohun

















