## TRS ABANDONRITE DAILY REPORT

ASE NAME AND UNIQUE ID: NORCEN N-49 Peel Plateau/ Eagle Plains												
CLIENT: NORCEN Wade Hartzell 231-0850							Date: Augugst	27, 1995	Project No. NORA068			
DAILY INSPEC	TION @ 11:00		regarding									
SAFETY MEET	ING @ 10:30		regarding Helic	garding Helicopter safety								
SHUT-IN PRES	SURES:		SITP	P N/A kPa SICP 0 kPa SCVP 0								
Is the wellhead a flanged wellhead $\Box Y / \Box N$ If no notify the office and complete wellhead schematic including serial # and press rating.												
MATERIALS TRANSFERRED: SERIAL #												
TRANSFERRED TO:												
TUBING:	Size	mm	# of jts. depth					in	out	tripping		
RODS:	Size	mm	# of jts. Scrapered D			// □N						
		mm	# of jts.		Scrapered []	(/ □N		· · · · · · · · · · · · · · · · · · ·				
Other	Other mm			# of jts.		Scrapered □Y/□N			out	tripping		
			FLU			HANDLING		L				
					Oil			Water	Produced		Water	
Fluid hauled to lea	ase						m³		m <sup>3</sup>			
from		····					I					
Fluid hauled from	lease	<u></u>					m <sup>3</sup>		m <sup>3</sup>			
to	· · · · · · · · · · · · · · · · · · ·						I		<u>l</u>			
					C	OSTS						
Code	Cost Description		С	ontractor		P.O. #		Ticket #	Amount	Fe	+ V/N	
						1.0				Amount Est. Y/N		
			***************************************									
Daily man hrs. (i	nc. travel)					Daily cost: (not inc. GST)						
Previous man ho	urs:					Previous cos		.,		_		
Cumulative man	hours:					Cumulative cost:			As per bid			
					DESCRIPTION	OF OPERAT	IONS		1.5 ps.	<u> </u>		
JOB OBJECTIV	E: Abandon Well	/ Clean location										
PRESENT OPER	RATION: Cleaning	g Lease				From/To		*****				
11:00 Arrive on location. Inspect well and location. All WH pressures zero. Lease has large platform on pilings. Platform consists of single and double planked 3"X10"'s. Begin to tear down platform for burning. Welder arrived @ 16:00 and began to cut off WH bolts. Tear down and stack platform for burning for remainder of day. Welder ran out of oxygen. SDFN @ 20:30												
EMERGENCY NUMBERS  AMPLILANCE OF THE SECOND												
AMBULANCE 911 RCMP 911 PROJECT MANAGER Scott Darling						TOOLPUSH  MOBILE						
Prepared by: Jim Quehl												
	<					Received by:					1	

## TRS ABANDONRITE DAILY REPORT

ZEASE NAME AND UNIQUE ID: NORCEN N-49 Peel Plateau/ Eagle Plains													
CLIENT:	NORCEN	Wade Hartzell		231-085	50			Date: Augugst 28	3, 1995	Project No. NORA068			
DAILY INSPECT	TION @ 09:00		regarding										
SAFETY MEETI	y - slinging												
SHUT-IN PRESS	URES:		SITP N/A kPa SICP 0 kPa SCVP 0 k										
Is the wellhead a flanged wellhead 🗆 Y / 🗆 N If no notify the office and complete wellhead schematic including serial # and press rating.													
MATERIALS TRANSFERRED: SERIAL #													
TRANSFERRED TO:													
TUBING:	Size	mm	# of jts.		depth			in	out	tripping			
RODS:	Size	mm	# of jts.		Scrapered 🗆 Y	7 🗆 N							
		mm	# of jts. Scrapered 🗆 Y			7 □N							
Other	<del>,, </del>	mm	# of jts.		Scrapered □Y/□N			in	out	tripping			
						HANDLING			1 11 3				
						HANDLING		Water		Produced Water			
Fluid hauled to lea					Oil	3	Water		m <sup>3</sup>		Produced water		
	SE			<u> </u>		m <sup>3</sup>			m- I				
	from						m³			m <sup>3</sup>			
Fluid hauled from	lease			<u>l,</u>		m_]			m				
to													
					C	COSTS							
Code	Cost Description			Contractor		P.O. #		Ticket #	Amount Est. Y/N		Est. Y/N		
						·							
Daily man hrs. (i	nc. travel)	,				Daily cost: (not inc. GST)							
Previous man ho	urs:					Previous cost:							
Cumulative man	hours:					Cumulative cost:			As per bid				
					DESCRIPTION	OF OPERATIONS	S						
JOB OBJECTIV	E: Abandon Wel	ll / Clean location											
PRESENT OPE	RATION: Cleanin	ng Lease / Cut & Ca	р			From/To							
09:30 Arrive on location. Inspect well and location. Continue tearing down platform and burning boards as well as digging around wellhead and dismantling wellhead to slingable size pieces. Cut off wellhead, fill top 10 m with cement and cap casing strings with 1/4" steel plate. Weld on marker sign, sling out WH in parts and backfill and level over excavation. Cut off and burn all pilings level with surface. Spread burnt ashes over lease and covered ashes and levelled lease with shale from shale pile. Leave location @ 20:00 hrs and fly to Eagle Plains.													
AMDIII ANCE	011	DCMD 011		EMEKGE	TOOL PUSH								
AMBULANCE PROJECT MAN	RCMP 911		···	TOOLPUSH MORE F									
PROJECT MANAGER Scott Darling						MOBILE HOME							
Prepared by: Jim Quehl						Received by:							