



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 20th July 1971

TO: The Oil Conservation Engineer:

RE: IOE Spring River YT N-58 *69-10-88 30*

Location: 69.13139°N., 138.73421 W. Status: D & A 1971 (Temperature Observation)

This location was inspected by the undersigned on 8th July 1971

T.D. 6997'

The location is in satisfactory/~~unsatisfactory~~ condition.


The following items require attention:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Clean-up crew left yesterday. Good job done.

Cellar should be filled in and all metal as shown in photograph completely covered. Because this well has thermistors in it, the back-filling will be done at a later date (from Ian Parker, IOL, Edmonton). When site visited again, paint identifier fluorescent orange.



Inspected by *M. D. Thomas*
M. D. Thomas
District 2