

Mining District: Dawson Mayo Watson Lake Whitehorse

Class 3 Class 4

Operator: SITKA GOLD CORP.

Property Name: Clear Creek

Permit #: LQ00494

NO WORK PERFORMED THIS SEASON

Activity Start Date: JAN 25, 2022

Total # of person days: 1,000

NTS #:
11SP14

Activity End Date: AUG 8, 2022

Maximum # of persons in camp at once: _____

DESCRIPTION OF ALL EXPLORATION: *(Attach additional pages as required)*

1. Construction of structures:
 Yes No

2. Construction of underground structures:
 Yes No

3. Corridors: L: _____ m x W: _____ m
 Yes No

4. Access roads per program:
 Yes No
 New Establishment Upgrading
L: 240 m
W: 8 m
**Please include GPS Coordinates (Latitude/Longitude points and/or Shape files)*

3 access spur roads for a total length of 240 m (nominally up to 8 m in width) were constructed on the Mary 42 & 44 claims in 2022 to accommodate skid mounted drill access as per the attached map and shapefile.

(1,380 m of access road was constructed under the permit in 2021, 0 m in 2020)

New access roads included shapefile: Clearcreek_2022_AccessRoads.shp

5. Establishment of trails per program:
 Yes No
L: _____ m
W: _____ m
**Please include GPS Coordinates (Latitude/Longitude points and/or Shape files)*

No new access trails were established during the 2022 season.

1,566 m of trail was built during the 2021 program under the current permit.

6. Fuel storage in a facility:
 Yes No

7. Fuel storage in a stationary container:
 Yes No
Total volume of fuel stored on site:
Gasoline: 100 L Diesel: 400 L Jet Fuel: _____ L Propane: _____ lbs

8. Lines: L: _____ m x W: _____ m
 Yes No

9. Number of clearings/claim (includes existing): 10 new clearings were created during 2022 on/adjacent access roads across 4 claims (Mary 9, 11, 42 & 44).
 Yes No
Surface area of each clearing: 8 m x 8 m

10. Off road use of vehicles:
 Summer Winter Both
none

11. Total volume of all trenching: 0 m³ Total number of trenches: 0
 Mechanical Hand Both L: _____ m x W: _____ m
Additional trenching details:
(if applicable)

12. Use of explosives - total kilograms: N/A _____

13. Use of vehicles on existing roads:
 Yes No
Pickup trucks, atv's, and heavy equipment

* Please include GPS Coordinates (Latitude/Longitude points and/or Shape files) and location maps for all disturbances from activities, and location(s) of any permafrost encountered.

DESCRIPTION OF OTHER EXPLORATION ACTIVITIES PERFORMED ON PROPERTY:

(include Bulk sampling update: total volume, royalties, etc. if applicable)

Project was limited to 4 diamond drillholes from 3 (2 new, 1 from 2021) road accessible setups during the winter portion of the program (February to March), and 16 diamond drillholes from 9 road setups (8 new) and 6 timbered heli-access setups during the summer portion of the program (June-Aug).

DESCRIPTION OF RECLAMATION ACTIVITIES PERFORMED ON PROPERTY:

4 of the 6 timbered heli-access drill pads were removed. No other reclamation was performed.

Required attachments: Wildlife Logs Photos Maps Shape files # of Pages: 1


Joel Gillham
Name

Project Geologist
Title

Signature



October 6, 2022
Date



396500

397000

397500

7085500

7085500

7085000

7085000

396500

397000

397500

MARY 11

MARY 9

YC84370

MARY 44

YC84368

MARY 42

YD05614

YD05612

MARY 45

