



Indian and Northern Affairs

Affaires indiennes et du Nord

Amoco - CRANSWICK W.S.

ACT. 02.

WELLSITE INSPECTION REPORT

Your file / Votre référence

Our file / Notre référence

DISTRICT:

DATE OF INSPECTION: 4-Sept

WELLSITE NAME: -MOCC PCP B-1 CRANSWICK YT A-42

WELLSITE LOCATION: 65° 41' 12.6" - 133° 07' 52.1"

DRILLING AUTHORITY: 507

RIG RELEASE DATE: PREPARING TO RELEASE RIG  
APR 15 → APR 15, 1973

STATUS: DAA

The location is in: ( ) Satisfactory (X) Unsatisfactory condition.  
(DRILLING RIG STILL OPERATING)

The following items require your attention:

- REMAINING CLEAN-UP FOLLOWING RIG REMOVAL
- 
- 
- 
- 
- 
- 
- 

Inspected by: .....

✓



90

~~105~~ 190  
20

WELLSITE INSPECTION REPORT

Oil file 4080 25547  
Water file 4080 25547

DISTRICT:

DATE OF INSPECTION:

WELLSITE NAME:

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in (  ) Satisfactory (  ) Unsatisfactory condition.

COMMENTS:

# 7 3 Rig  
# 8 9 ~~to~~  
# 9 10 Camp

RIG SUSPENDED ON LOC.

INSPECTED BY:

M. D. Thomas  
Regional Oil & Gas Engineer

DRG

✓

✓











