



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

N-7940-1-277

File No.
Drilling Authority No. 277

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Canoe R Chance YT J-19

Location: 66° 08' 31.2"N., 137° 32' 28.02"W Status: Suspended Gas and Oil 1968

This location was inspected by the undersigned on 9th July 1971

T.D. 4745'

The location is in ~~satisfactory~~ / unsatisfactory condition.

The following items require attention:

1. Provide identifier
2. Remove planking around wellhead and backfill
3. Pile and burn all lumber
4. Bury or remove some 50 steel drums.
5. Remove storage tank
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)







