



WELL-SITE INSPECTION - RAPPORT D'INSPECTION DE
REPORT - L'EMPLACEMENT DU Puits

Drilling authority No.
Permis de forage N° 306

From: Field Office or Area - Bureau régional ou zone

De: COGLA - Yellowknife, N.W.T.

Date
July 25, 1988

To: The Oil Conservation Engineer:
À: L'ingénieur (Conservation des hydrocarbures):

RE:
Au sujet de: Canoe River East Chance Y.T. C-18

Location - Emplacement
66° 07' 08.935"N 137° 17' 57.42"W

Statut - État
D & A

This location was inspected by the undersigned on
L'emplacement a été inspecté par le soussigné le July 20, 1988

The location is in satisfactory unsatisfactory condition
L'état de l'emplacement est satisfaisant insatisfaisant

The following items require attention - Porter une attention spéciale aux articles suivants:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Other comments and recommendations : (include map, if necessary for clarity) - Autres commentaires et recommandations (ajouter des cartes géographiques au besoin)

The lease is clean with about 40% vegetation growth.
A roll of drilling line on a spool was located about 200 metres from the well.
The sign was set back up during the inspection.
The casing has not been cut off.
2 photos taken.

Bunce Kirk
Inspected by - Inspecteur



ONE RIVER
BANDAGE
100 FT
100 FT

