



WELLSITE INSPECTION REPORT

Your file Votre référence

Our file Notre référence

DISTRICT: 2

DATE OF INSPECTION: 3 Sept., 1972

WELLSITE NAME: Inexco et al Mallard YT O-18

WELLSITE LOCATION: 65°47'58" N 140°17'41" W

DRILLING AUTHORITY: 598

RIG RELEASE DATE: _

STATUS: _ *SUSPENDED*

The location is in: () Satisfactory (x) Unsatisfactory condition.

The following items require your attention:

GENERAL AREA CLEANUP REQUIRED

FOLLOWING RIG CAMP REMOVAL

Inspected by:

✓



53

WELLSITE INSPECTION REPORT

See the notes on the
your file, votre dossier

DISTRICT:

2

DATE OF INSPECTION:

3

WELLSITE NAME:

Inexo Mallard YT 0-18

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in () Satisfactory

(X) Unsatisfactory condition.

COMMENTS:

23 of Loc & Rif
24 of " " "

Rif & camp still on hole.

INSPECTED BY:

M. D. Thomas
Regional Oil & Gas Engineer

✓
U



