



WELLSITE INSPECTION REPORT

Your file    Votre référence

Our file    Notre référence

DISTRICT: 2

DATE OF INSPECTION: 3 Sept., 1972

WELLSITE NAME: Socony Mobil Western Minerals E. Porcupine R. YT K-56

WELLSITE LOCATION: 66°05'33.42" N      137°55'32.15" W

DRILLING AUTHORITY: 118

RIG RELEASE DATE: 23 July, 1963

STATUS: D & A

The location is in: (.) Satisfactory    (x) Unsatisfactory    condition.

The following items require your attention:

- 1. Several Drums to be removed.
- 2. BARRAGE TO BE FURLED OR REMOVED.
- 3. WELL IDENTIFIER PLATE TO BE INSTALLED.
- 4. Pipe, metal & wooden shafts, to be removed.

Inspected by: .....

✓



56

WELLSITE INSPECTION REPORT

sur le nom dossier  
your file votre dossier

DISTRICT:

2

DATE OF INSPECTION:

3

WELLSITE NAME:

SOCONY MOBIL E PORCUPINE YT K-56

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in ( ) Satisfactory

(X) Unsatisfactory condition.

COMMENTS:

#30 of wellsite with piles

#31

#32

#33 Garbage Drums etc

No identification

INSPECTED BY:

M. D. Thomas  
Regional Oil & Gas Engineer

✓

✓

✓















