



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil - WM Blackie No. 1 YT M-59 CE-00-137 CC

Location: 65.97193°N., 137.18635°W. Status: Suspended Gas Well March 1964

This location was inspected by the undersigned on 9th July 1971

T.D. 6,338'

The location is in ~~an~~ unsatisfactory condition.

The following items require attention:


1. Remove planking around cellar and backfill.
2. Provide identifier
3. Pile all lumber and burn
4. Bury or remove all drums, iron and other junk.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Lease never cleaned up. Junk all over.

Lock on valve.

No identification on wellhead.



Inspected by *M. D. Thomas*
M. D. Thomas
District 2