



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: September 21, 1972

~~XX~~

RE: Socony Mobil Western Minerals Blackie No. 1 YT M-59 (66-00-137-00)

Location: 65-58-55 — 137-11-11 Status: Suspended ? 27-3-64

This location was inspected by the undersigned on August 24, 1972

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. Piles of junk and/or scrap metal to be buried.
2. Garbage pit to be buried.
3. Pile of cement to be buried.
4. Pile of wood to be buried.
5. Drill cuttings to be levelled.
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

There are 11 individual piles of garbage, junk and/or scrap metal.
This lease is in very good condition except for above.

Inspected by [Signature]