



WELLSITE INSPECTION REPORT

DISTRICT:

DATE OF INSPECTION: 3-Sept-72

WELLSITE NAME: SOCONY MOBIL MOLAR^{W.M.} Y.T. P-34

WELLSITE LOCATION: 67° 03' 39" — 138° 36' 00"

DRILLING AUTHORITY: 138

STATUS: RR 13-8-64

The location is in (X) Satisfactory

() Unsatisfactory condition.

COMMENTS: .

INSPECTED BY:

M. D. Thomas
Regional Oil & Gas Engineer



48

WELLSITE INSPECTION REPORT

sur le votre dossier
your file, votre dossier

DISTRICT:

2

DATE OF INSPECTION:

3

WELLSITE NAME:

Socomy Mobil Molan 45 P-34

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in (X) Satisfactory () Unsatisfactory condition.

COMMENTS:

12 of identification
13 of equipment near runway

INSPECTED BY:

M. D. Thomas
Regional Oil & Gas Engineer

✓
X

5



