

Page 19

Photos 1 and 2 are of Shell Trail River YT H-37, ADW 0728. This well was drilled in 1973 and abandoned in 1974. The down hole abandonment is satisfactory. I have no concerns with this well.

Photos 3 and 4 are of Chevron SOBC WM N YT D-61, ADW 0565. This well was drilled in 1972 and abandoned in 1972. These casings have been cemented to surface and the down hole abandonment is satisfactory. The 482.6mm cooling conductor is approximately 0.6m above ground. The pipe from the rat hole and mouse hole is sticking up approximately 1.0m. The down hole abandonment is satisfactory. I have no concerns with this well.

No photographs

We flew from the D-61 location to Shell Peel R. YT H-59, ADW 0266. This well was drilled in 1967 and abandoned in 1967. We were unable to locate the wellsite. No photographs were taken of this area. We flew over the area indicated by the coordinates on file but were unable to identify any evidence of a drilling location. Due to fuel shortage we were unable to extend our area of search. The well file indicates that the well was properly abandoned down hole and the surface abandonment was completed according to the regulations.

No photographs

We flew from the H-59 location to Shell Peel R. YT 2B-06, ADW 0237. This well was drilled in 1967 and abandoned in 1967. We were unable to locate the wellsite. No photographs were taken of this area. We flew over the area indicated by the coordinates on file but were unable to identify any evidence of a drilling location. Due to fuel shortage we were unable to extend our area of search. We landed in an area that had possibilities but due to over growth and river channels we were unable to confirm the possibility of a drill site. The well file indicates that the well was properly abandoned down hole and the surface abandonment was completed according to the regulations.

Page 20

→ Photos 1 and 2 are of Socony Mobil WM Ellen YT C-24, ADW 0144. This well was drilled in 1964 and abandoned in 1965. The down hole abandonment is satisfactory. I have no concerns with this well.

Page 21

Photos 1, 2 and 3 are of Shell Peel R. YT L-01, ADW 0210. This well was drilled in 1965 and abandoned in 1966. On this location we did not land. It appears that the well was abandoned approximately 1.0m above ground level. The 508mm casing has been cut off leaving the 244.4mm casing is enclosed with cement used to for cementing the 508mm casing in place. The down hole abandonment is satisfactory. I have no concerns with this well.

Photo #4 is of Dave Downing, Imre Varga and Normand Tremblay. Taken for future reference.









S. A. W. A.

E. L. E. E.

Y. T. S. - 2

SAWA
ELE
Y.T. S-2





