



WELLSITE INSPECTION REPORT

Your file Votre référence

Our file Notre référence

DISTRICT: 2

DATE OF INSPECTION: 3 Sept., 1972

WELLSITE NAME: Socony Mobil Western Minerals Whitestone YT N-26

WELLSITE LOCATION: 66°05'59" N 138°20'__" W

DRILLING AUTHORITY: 139

RIG RELEASE DATE: 6 Aug., 1964

STATUS: D & B

The location is in: () Satisfactory (x) Unsatisfactory condition.

The following items require your attention:

1. File of PUMP MATERIALS & WIRE
cable to be covered or removed.
2. File of LOGS (about 13), cable, thread protectors,
and concrete chunks - to be removed.

Inspected by:



55

WELLSITE INSPECTION REPORT

DISTRICT:

2
3

DATE OF INSPECTION:

WELLSITE NAME: SOCONY MOBIL WHITESTONE ET N-26

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in () Satisfactory

(X) Unsatisfactory condition.

COMMENTS:

27 of wellhead
28 of pile of burnt material
29 of Drum

pile contains wire rope. Pile should be buried.

INSPECTED BY:

M. D. Thomas
Regional Oil & Gas Eng





