



WELLSITE INSPECTION REPORT

Your file Votre référence

Our file Notre référence

DISTRICT:

DATE OF INSPECTION: 4-Sept-72

WELLSITE NAME: MCD GEO. NORTHUP TAYLOR LK YT K-15

WELLSITE LOCATION: 65° 54' 39" --- 135° 03' 00"

DRILLING AUTHORITY: 330

RIG RELEASE DATE: 29-3-69

STATUS: D/A

The location is in: () Satisfactory (X) Unsatisfactory condition.

The following items require your attention:

1. Further geologic data required in & around dump & around well.

Inspected by:



95
42

89

WELLSITE INSPECTION REPORT

DISTRICT:

2

DATE OF INSPECTION:

4

WELLSITE NAME:

~~McD~~ GCO Northup Taylor Lake ^{VT} K-15

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in (/) Satisfactory

(X) Unsatisfactory condition.

COMMENTS:

#56 of identifier

#67 of Dump with garbage

This should be cleaned up further - both around
markers and Dump.

INSPECTED BY:

A considerable amount of work has been
done. Why wasn't Dump cleaned up?

M. D. Thomas
Regional Oil & Gas Engineer

✓

✓

U

