

TRAINING AND SERVICE RIG INSPECTION REPORT

Date of Inspection 13 March 77 Date of last inspection

Well Name Pacific at the Well 47 F-87 Location 66 9900, 134 86500

Operating Company Pacific Contractor Gustarson Rig No. 11

Operation in Progress Drilling Depth 7758

Spud Date 13 Feb 77 D.A. No. 547 Projected Total Depth 11,000

Depth of last casing string 1378 @ 1100

Toolpusher Jim Quirk Operators Representative Bill Jarman Conservation Engineer M. D. Thomas

Signature [Signature] Signature

N.B.: See Page 2 - Remarks re items checked as 'Unsatisfactory' or 'No'.

I. GENERAL

- 1. D.A. posted Yes No
- 2. Tour Reports complete, up to date and signed. Yes No
- 3. Location of wellsite with respect to natural & installed facilities. Yes No
- 4. Sump adequately contained Yes No
- 5. Housekeeping Yes No
- 6. Radio communication in working order. Yes No
- 7. Camp & kitchen facilities clean and sanitary. Yes No
- 8. Adequate waste disposal Yes No
- 9. Deviation surveys every 500' minimum and recorded in tour book. Yes No

II. SAFETY

- 1. Flare pit and burn pit greater than 150' from wellbore. Yes No
- 2. Boilers greater than 150' from the wellbore. Yes No
- 3. Rig lights operating and with protective covers. Yes No
- 4. Electrical fixtures within 75' of wellbore explosion proof. Yes No
- 5. Power plant grounded. Yes No
- 6. Adequate gas masks; Type: 6 Scott Yes No
- 7. Regulator with adequate supply of air. 2 Yes No
- 8. Minimum of two 20# powder fire extinguishers in galloping. Yes No
- 9. Minimum of 2 fire extinguishers in man boiler area. Yes No
- 10. Fire extinguishers in camp. Yes No
- 11. Fire extinguishers; No. 2 Yes No
- 12. Safety goggles Yes No
- 13. Stretcher and blankets 2 Yes No
- 14. All moving parts safely guarded Yes No
- 15. Safety harness rails in place Yes No
- 16. Safety harness rails and pressure in good shape. Yes No
- 17. Safety harness greater than 75' from wellbore. Yes No
- 18. Safety harness and wellbore floor Yes No

- 20. Waterproof material in rig shelter Yes No
- 21. Wiring high enough above ground for clearance. Yes No
- 22. Hard hats worn on rig or in potentially dangerous areas. Yes No
- 23. All breathing apparatus tested monthly & recorded in tour book. Yes No

III. MUD SYSTEM

- 1. Mud tank capacity 400 bbl Yes No
- 2. Safety valve on pump discharge line Type: Dance 3" Scott Yes No
- 3. Mud weight relative to depth. 9.0 # Yes No
- 4. Gas analyzer. Yes No
- 5. Degasser, if mud tanks in rig shelter. Yes No
- 6. Mud level warning system. Type: Dance Yes No
- 7. Condition of Kelly hose. Yes No
- 8. Mud mixing platform clean. Yes No
- 9. Studs and nuts on fluid cylinder head and valve covers. Yes No
- 10. Pressure rating of mud discharge line Yes No
- 11. Mud gun anchors. Yes No

IV. MACHINERY AND PUMP

- 1. Condition of motors Yes No
- 2. Engine air inlets greater than 40' from wellbore. Yes No
- 3. Engine exhausts greater than 40' from wellbore. Yes No
- 4. Where engine exhausts exceed 400°F., open exhausts less than 75' from wellbore are insulated. Yes No
- 5. Guard safety and down on floor. Yes No
- 6. Condition of fuel lines. Yes No
- 7. Shut-off checked weekly and recorded on log sheets. Yes No
- 8. Water connections on engine exhausts working. Yes No

V. HOIST AND DRUMS

- 1. Drilling valves ready. Yes No
- 2. Drilling operation. Yes No
- 3. Drilling operation. Yes No
- 4. Drilling operation. Yes No
- 5. Drilling operation. Yes No
- 6. Drilling operation. Yes No
- 7. Drilling operation. Yes No
- 8. Drilling operation. Yes No

7. Pick up slings	<input checked="" type="radio"/> Yes	<input type="radio"/> No	12. BOP's tested before drilling out.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
8. Top exits from pump house	<input checked="" type="radio"/> Yes	<input type="radio"/> No	13. BOP stack enclosed and heated.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
9. Top exit from monkey board	<input checked="" type="radio"/> Yes	<input type="radio"/> No	14. Manifold outside substructure enclosed and heated.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
10. Condition of hook latch	<input checked="" type="radio"/> Yes	<input type="radio"/> No	15. Blind bolts in place & tightened	<input checked="" type="radio"/> Yes	<input type="radio"/> No
11. Are derrick floor exits open outside from floor.	<input checked="" type="radio"/> Yes	<input type="radio"/> No	16. High pressure lines, valves, fittings used on BOP's.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
12. Stabbing valve adapters	<input checked="" type="radio"/> Yes	<input type="radio"/> No	17. Feasibility of control valve handles.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
13. Escape buggy checked weekly and recorded.	<input checked="" type="radio"/> Yes	<input type="radio"/> No	18. Control arms for manually closing ram type preventer outside substructure.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
<u>VI. PREVENTER</u>			<u>VII. ELECTRICAL</u>		
1. S.I. time on bag type preventer	<input checked="" type="radio"/> 3	MS	19. High pressure lines, valves, fittings on remote control unit.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
2. S.I. time on rams	<input checked="" type="radio"/> 3	MS	20. Remote controls for BOP's greater than 75' from wellbore.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
3. Pressure test on bag type preventer.	<input type="radio"/> 3	MS			
4. Pressure test on pipe rams.	<input type="radio"/> 3	MS			
5. Pressure test on blind rams.	<input type="radio"/> 3	MS			
6. Valves open to manifold.	<input checked="" type="radio"/> Yes	<input type="radio"/> No	1. All light fixtures and wiring in good condition	<input checked="" type="radio"/> Yes	<input type="radio"/> No
7. Flareline tied down.	<input checked="" type="radio"/> Yes	<input type="radio"/> No	2. Light plant adequate for job.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
8. Accumulator hydraulic reservoir	<input checked="" type="radio"/> 3	MS	3. Standby light plant.	<input checked="" type="radio"/> Yes	<input type="radio"/> No
9. Standby pressure source - ie: Nitrogen	<input checked="" type="radio"/> 3	US			
10. BOP drill witnessed	<input checked="" type="radio"/> Yes	<input type="radio"/> No			
11. General crew knowledge of blowouts and kicks.	<input checked="" type="radio"/> 3	US			

* Satisfactory
** Unsatisfactory

REMARKS RE- ITEMS CHECKED AS 'UNSATISFACTORY' OR 'NO':

To 16 Future safety meetings will be recorded in log book.
 18 Not sure whether every driller has first aid certificate. See Section 94 of the Canada Oil & Gas Drilling and Production Regulations and provide the District Conservation Engineer with proof of compliance.
 23 Test breathing apparatus monthly & record in log book.
 6 Ok Exits from 3 sides.
 13 Escape buggy to be checked weekly & recorded. Do not ride buggy.
 General: This rig is the cleanest and warmest rig visited in the North.