

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: SHELL PEELE R. YT J-21

Location: 66.50886° N., 134.07104° W. Status: DPA Sept. 1965

This location was inspected by the undersigned on _____

The location is in satisfactory/unsatisfactory condition. TD 4000'

The following items require attention:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Landed at what appeared to be a lease but nothing found.

Very clean.

If known, a description of terrain and condition of lease should be provided to aid in locating lease on next inspection trip.

No pictures taken.

Inspected by H.D. Thomas

Original to Oil Conservation Engineer, Dept of IA & ND, Duplicate to Field Office or Inspecting Engineer. H.D. Thomas, District 2