



TO - Pinnacle Petc.

WELLSITE INSPECTION REPORT

Your file / Votre référence

Our file / Notre référence

DISTRICT:

"Pinnacle" operator

DATE OF INSPECTION: 4-Sept-72

WELLSITE NAME: Toltec River YT N-77

WELLSITE LOCATION: 65° 56' 46" - 134° 29' 12"

DRILLING AUTHORITY: 321 RIG RELEASE DATE: 23-7-70

STATUS: D & A

The location is in: () Satisfactory Unsatisfactory condition.

The following items require your attention:

1. Well IDENTIFIER Plate To be INSTALLED.
2. No lease work done since 1971 INSPECTION
 - a) REMOVE DRUMS & RAFT ALONG SHORELINE
 - b) Remove drums on site
 - c) Remove lumber & camp shacks

Inspected by:



88

195
16

WELLSITE INSPECTION REPORT

DISTRICT:

2

DATE OF INSPECTION:

4

WELLSITE NAME:

~~88~~

Toltec well R 77 H-77

WELLSITE LOCATION:

DRILLING AUTHORITY:

STATUS:

The location is in (A) Satisfactory

(F) Unsatisfactory condition.

COMMENTS:

#34 where well identifier is
supposed to be

#35 shades & drums etc

Shades belong to Indians.

INSPECTED BY:

Nothing done on this lease since last
inspection.

M. D. Thomas
Regional Oil & Gas Engineer

✓

✓

U



