



File No.
Drilling Authority No. 431

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT
OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Western Minerals N Hope YT N-53 610-40-138-15

Location: 66.54833° N., 138.42500° W. Status: D & S. 1970

This location was inspected by the undersigned on 9th July 1970

T.D. 14,043'


The location is in ~~good~~/unsatisfactory condition.

The following items require attention:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Rig still on hole with all attendant paraphernalia.
Identifier in place.
Nabors Drilling Ltd. rig.



Inspected by M. D. Thomas

M. D. Thomas
District 2