



**BJ SERVICE DIV**  
**BORG-WARNER (CANADA)**



TESTING REPORT



45 LANDING SUB		
<del>CO</del> <u>CO</u>	1.00	
45 TOOL OR P.O. SUB	1.00	
CO SUB	4.00	
SHUT IN TOOL	5.20	
R.F.S. No. <u>11</u>	3.30	
R.F.S. No.		
HYDRAULIC TOOL	7.20	
JARS	6.00	
RECORDER No. <u>2064</u>	5.00	DEPTH <u>8033</u>
RECORDER No.		DEPTH
SAFETY JOINT	1.75	
BY PASS SUB		
PACKER	6.00	
PACKER	5.00	TOTAL TOOL ABOVE INTERVAL <u>45.40</u>
ANCHOR—SPECIFY	1.00	
ANCHOR—SPECIFY		
ANCHOR—SPECIFY		
BLANK OFF OR BY PASS SUR		
RECORDER No.		DEPTH
PACKER		TOTAL INTERVAL <u>72.40</u>
PACKER		
ANCHOR—SPECIFY <u>Perf</u>	31.00	
ANCHOR—SPECIFY		
ANCHOR—SPECIFY		
RECORDER No. <u>2013</u>	5.00	DEPTH <u>3091</u>
RECORDER No.		DEPTH
<u>Drilling Collar</u>	31.40	
<u>CO</u>	1.00	
BULLNOSE	3.00	TOTAL TAIL PIPE <u>70.40</u>

1. PACKER DEPTH 30.40

2. PACKER DEPTH 30.40

3. PACKER DEPTH


4. PACKER DEPTH

TOTAL DEPTH 31.00

DST CHARTS FOR COMPARATIVE VISUAL ANALYSIS

TOTAL TAIL PIPE 70.40

TOTAL TEST TOOL 117.35



B HIGH PERMEABILITY STRONG DAMAGE EFFECT    HIGH PERMEABILITY NO DAMAGE EFFECT    MEDIUM PERMEABILITY STRONG DAMAGE EFFECT    MEDIUM PERMEABILITY NO DAMAGE EFFECT    LOW PERMEABILITY STRONG DAMAGE EFFECT    LOW PERMEABILITY NO DAMAGE EFFECT



